


Common Spindles Probe T# not mounted Clear Hist

General Settings

Motion Settings

Probing Ver Debug Setup

Touch:


 Max Dist:

 Gage/Plate Height:

 TP Delay:

 TC Pos:


 Rnd Diam:

 Max Dist:

 TP Z [MC]:

Axes Enabled

Rotation Radius

Over Rides

Special Functions

In 4:

Misc Config

Encoder DRO Setting

	Current Pos'n	Encoder Pos'n	
X:	<input type="text" value="-7.4416"/>	<input type="text" value="-2.5681"/>	<input type="button" value="Zero"/>
Y:	<input type="text" value="-1.9766"/>	<input type="text" value="-3.1860"/>	<input type="button" value="Zero"/>
Z:	<input type="text" value="-8.6289"/>	<input type="text" value="-6.6260"/>	<input type="button" value="Zero"/>

Ref Point (Machine Coords)

X:

 Y:

 Z: